


1. Approving Competent Authority / Country
 CIVIL AVIATION AUTHORITY
 United Kingdom

2. AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

3. Form Tracking Number
 BA32874679

4. Organisation Name and Address

 British Airways Avionics Engineering.
 Ely Meadow, Talbot Green,
 Pontyclun, Cardiff CF72 8XL

5. Work Order/Contract/Invoice
 4518093
 R327842

6. Item	7. Description	8. Part number	9. Qty	10. Serial No.	11. Status/Work
1.	SMOKE DETECTOR (VITAL)	2156-204A	1	8038	Repaired


12. REMARKS : Batch No 0005824991
 Reason for removal confirmed - 'SMOKE DETECTOR FAULT'
 Spare bulb & grommet missing.
 Fitted: bulbs(x2) & grommet.
 Unit given final test - satisfactory IAW ATA:26-16-04 ATP:07546 REV:9
 Unit released under TCCA Approval No. 808-04

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. BT7Y404J

U129340 13.10.2017 Original
 Manufacturer : AUTRONICS CORP&space(5)

13a. Certifies that the items identified above were manufactured in conformity to:
 approved design data and are in condition for safe operation
 non-approved design data specified in block 12

14a. PART-145.A.50 Release to service Other Regulation specified in block 12

14b. Authorised Signature


14c. Certificate/Approval Ref. no.
 UK.145.00142

14d. Name U129340
 Ian Williams Clement BAAE 416 CRS

14e. Date(dd/mm/yyyy) 13.Oct.2017

13b. Authorised Signature

13c. Approval/Authorisation Number

13e. Date(dd/mm/yyyy)

14d. Name U129340
 Ian Williams Clement BAAE 416 CRS

14e. Date(dd/mm/yyyy) 13.Oct.2017

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).
 Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
 Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Ely Meadow, Talbot Green,
Pontyclun, Cardiff
CF72 8XL
GB

Component Strip Report

Customer: AJW AVIATION

The Headquarters, Maydown Avenue
Slinfold, West Sussex
RH13 0AS

Part Number: 2156-204A:03972

Serial Number: 8038

Description: SMOKE DETECTOR (VITAL)

Repair Order Number: R327842

Order Number: 4518093

Equipment Number: 42064759

Batch Number: 0005824991

Warranty Requested:

Customer WORK REQUIRED :

Date of Receipt: 09.10.2017

Reason for Removal:

Removal Code: W474 FE

Reason for removal: FWD CARGO SMOKE DETECTOR FAULT

Date Serviceable: 13.10.2017

Reason for removal confirmed - 'SMOKE DETECTOR FAULT'

Spare bulb & grommet missing.

Fitted: bulbs(x2) & grommet.

Unit given final test - satisfactory IAW ATA:26-16-04 ATP:07546 REV:9

Unit released under TCCA Approval No. 808-04

Warranty Decision:

Tested

Repaired

Overhauled

Inspected

Re-manufactured

New

Modified

Certification Number: BA000032874679