





<b>1. Approving Competent Authority/Country</b> <b>CAA/UNITED KINGDOM</b>		<b>2.</b> <b>AUTHORISED RELEASE CERTIFICATE</b> <b>EASA FORM 1</b>		<b>3. Form Tracking Number.</b> <b>146272</b>	
<b>4. Organisation Name and Address.</b> <b>MUIRHEAD AEROSPACE LIMITED</b> <b>T/A MUIRHEAD AVIONICS</b> Muirhead Aerospace Ltd 3 The Square Heathrow Southall Lane, Southall, Middlesex UB2 5NH UNITED KINGDOM		<b>5. Work Order/Contract/Invoice</b> <b>Work Order No:</b> GA12111 <b>Customer Order No:</b> R269748			
<b>6. Item</b> 1	<b>7. Description</b> G6074 VHF COMM CONTROL PANEL	<b>8. Part No.</b> G6074-05	<b>9. Qty.</b> 1	<b>10. Serial No.</b> 260	<b>11. Status/Work</b> Repaired
<b>12. Remarks</b> Manual ID: 23-11-05, Revision #: 7, Revision Date: 28/02/2003 14 CFR 43.9 Return to Service The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. H9EY443N Date(m/d/y): Sep/01/2015 Signed:  					
<b>13a. Certifies that the items identified above were manufactured in conformity to:</b> <input type="checkbox"/> approved design data and are in a condition for safe operation. <input type="checkbox"/> non-approved design data specified in block 12 Repair report attached reference GA12111 TCCA Approval Ref: 807-07					
<b>13b. Authorised Signature:</b>		<b>13c. Approval/Authorisation No.</b>		<b>14a.</b> <input checked="" type="checkbox"/> Part-145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.	
<b>13d. Name</b>		<b>13e. Date (dd mmm yyyy)</b>		<b>14b. Authorised Signature</b>  	
<b>14c. Certificate/Approval Ref No.</b> UK.145.00592		<b>14d. Name</b> D. UNDERWOOD		<b>14e. Date (dd mmm yyyy)</b> 01 Sep 2015	
<b>USER/INSTALLER RESPONSIBILITIES</b> This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.					



Muirhead Aerospace Limited

Contact Name: Customer Services
Telephone: +44 (0)20 8571 3422
Fax: +44 (0)20 8571 2336

Tear Down/Inspection

Work Order #: GA12111
Date Printed: 31-Jul-15
Work Type: Repaired
Page: 1

To:
ATTN: ADAM DUMMER
AJ WALTER (AVIATION) LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX RH13 0SH

Ship To:
AJ WALTER (AVIATION) LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD
WEST SUSSEX, RH13 0SH UK

Cust.PO Ref.: R269748
Cust.Code: 200382

Cust.Phone:
Cust.Fax:

Cust.Email:
Station: SOUTH

Part No. In: G6074-05
Part No. Out: G6074-05
TSO: 0

TSN: 0

TSR: 0

CSO: 0

CSN: 0

CSR: 0

Description: G6074 VHF COMM CONTROL PANEL Qty: 1
Serial No: 260 Previous WO No:

Documentation: 23-11-05
ATA No: 23-11-05

Location: GABLES SHELF
Rev. & Date: 7 28-Feb-2003

Symptoms:
REPORT

REASON FOR REMOVAL:- CTR VHF COMM PNL LEFT FREQ DISPLAY READOUT BLANK.

PRELIMINAQRY CHECKS CONFIRMED THE REPORTED DEFECT, ALSO NOTED LIQUID INGRESS, AND LIGHTING U/S.

INSPECTION FOUND COFFEE TYPE INGRESS, L/H LCD FAULTY, LIGHTING CIRCUIT LAMPS, AND LCD BACK LAMPS OPEN CIRCUIT.

FORE-MENTIONED DEFECTIVE PARTS REPLACED, UNIT CLEANED, INSPECTED AND FULLY TESTED I.A.W. THE MANUFACTURER'S SPECIFICATION AND IS FOUND TO BE OPERATING SATISFACTORILY.

Inspection Signature:


[Handwritten Signature]

Stamp:

[Handwritten Stamp]

Inspect. Print Name:

[Handwritten Name: P.S. Dhanjal]

Job No: <b>GA12111</b>	<b>Work Order Scope and Traveller</b> <b>Muirhead Aerospace Limited</b>	Date Printed: 29-Jul-15 Time: 3:30:21 PM Page: 1 of 1	
Part No: G6074-05 Cust Code: 200382 OEM: GABLES	Description: G6074 VHF COMM CONTROL PAN Qty: 1 Customer Name: AJ WALTER (AVIATION) LTD Date In: 27-Jul-15	Serial No: 260 Cust Ref No: R269748 Due Date: 04-Aug-15 Scheduled Date:	
Documentation Used: 23-11-05	ATA#: 23-11-05	Rev#: 7 28-Feb-2003	
Task: <b>WORK CARRIED OUT</b>	Est. Time: 0	Sequence: 1	
OP1. Visual Inspection: Warranty seal intact Yes [ ] No <input checked="" type="checkbox"/>	D.O.M: MAR 1993	Tech. JFG	Insp.
OP2. Functional Test: Reported Defect Confirmed Yes <input checked="" type="checkbox"/> No [ ] UNSAT		JFG	
OP3. Malfunction Cause and Corrective Action:			
① EXTERNAL VISUAL CHECKS SATISFACTORY. AFI M.I.EE SEALS BROKEN. -		JFG	
② COVERS REMOVED. INTERNAL VISUAL CHECKS REVEAL EVIDENCE OF LIQUID (COFFEE) INGRESS. -		JFG	
③ LIGHTING CHECK REVEALS LAMPS O/C (8 PLACES)		JFG	
④ LCD BACKLIGHT LAMPS O/C (2 PLACES)		JFG	
⑤ COFFEE RESIDUE REMOVED FROM INTERNAL COMPONENTS		JFG	
⑥ LAMPS REPLACED (9 PLACES)		JFG	
⑦ FUNCTION TEST REVEALS LM LCD FAMILY.		JFG	
⑧ LCD AND ZEBRA STRIPS REPLACED.		JFG	
⑨ UNIT TESTED (AW) CMM 23-11-05 REV 7 DATED 28 FEB 2003, SATISFACTORY		JFG	
OP4. Mods / SBs / ADs Embodied:	None	JFG	
OP5. Pre-Case FOD / Loose Articles Check:	No FOD FOUND	JFG	
OP6. Final Inspection and Test: Inspected By:  Date: 31 July 2015	Overhauled: [ ] Modified: [ ] Calibrated: [ ]	Repaired: <input checked="" type="checkbox"/> Inspected/Tested: <input checked="" type="checkbox"/> Readout: [ ]	Final Insp.