


1. Approving Competent Authority / Country: <b>United Kingdom</b> <b>Civil Aviation Authority</b>		<b>AUTHORISED RELEASE CERTIFICATE</b> <b>EASA FORM 1</b>				3. Form Tracking Number: <b>L 2999057</b>
4. Organization Name and Address: <b>Panasonic</b> Panasonic Avionics Corporation Quadrant House, Heron Drive, Pariaunt Road, Langley Berks, SL3 8XP, UK		8. Part No. RD-AX1302-13		9. Qty. 1	10. Serial No. D606492	5. Work Order/Contract/Invoice R329316
6. Item 1	7. Description MAIN MULTIPLEXER			11. Status / Work REPAIRED		
12. Remarks ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-34-58 REV 15 DTD JAN 2009. PLEASE REFER TO SR NUMBER 4921418.						
Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X. Panasonic Avionics Corporation internal reference <b>SR4921418</b>						
13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in a condition for safe operation. <input type="checkbox"/> non-approved design data specified in block 12.						
13b. Authorised Signature:		13c. Approval/Authorization Number		14a. <input checked="" type="checkbox"/> PART 145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.		
13d. Name		13e. Date (dd mmm yyyy)		14b. Authorized Signature: 		
USER/INSTALLER RESPONSIBILITIES				14c. Certificate/Approval Ref No: <b>UK.145.00297</b>		
This certificate does not automatically constitute authority to install the item(s). Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1. Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.		14d. Name Mick White		14e. Date (dd mmm yyyy) 13-NOV-2017		



**Panasonic Avionics Corporation**

Quadrant House, Heron Drive, Parlaunt Road,  
Langley Berks, SL3 8XP, UK.

Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

**REPAIR REPORT / DELIVERY ORDER**

**SOLD TO** AJ WALTER AVIATION  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD, ENGLAND RH13 0AS, GB

**SHIP TO** AJ WALTER AVIATION  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD, ENGLAND RH13 0AS, GB



PAGE 1 of 1

**SHIP TRANSACTION:**

CUSTOMER P.O. NUMBER <b>R329316</b>		CUSTOMER <b>1001</b>	TAIL NO. <b>A40-BP</b>	CUST PROD REF <b>5600185</b>	SERVICE REQUEST <b>4921418</b>	
PART NUMBER <b>RD-AX1302-13</b>		NOMENCLATURE <b>MAIN MULTIPLEXER</b>			DATE REMOVED	DATE RECEIVED <b>06-NOV-2017</b>
SERIAL NUMBER <b>D606492</b>		DATE OF MFG <b>30-SEP-2007</b>	WTY START DATE <b>27-SEP-2007</b>	WTY END DATE <b>26-SEP-2010</b>	DATE REPAIRED <b>10-NOV-2017</b>	SHIP DATE
MOD IN <b>1-3</b>						
REASON FOR CUSTOMER REJECTION	<b>1 WORKSTEP ADDED BY 30548 ON 04.OCT.2017, 09:10. ALL SEATS AUDIO INOP. ALL CABIN SEATS AUDIO SOUND INOP....CONTINUED...</b>					
INTERNAL INSPECTION	<b>No Physical Damage</b>					
EXTERNAL INSPECTION	<b>Physical Damage - MINOR MARKS ON COVERS, NO ACTION TAKEN.</b>					
ACTUAL FAILURE / CORRECTIVE ACTION	<b>UNIT FAILED COMMUNICATION TEST; MAIN CARD FAULTY. REPORTED FAILURE CONFIRMED. REPLACED MAIN CARD. UNIT CLEANED, TESTED AND PASSED ALL FUNCTIONAL TESTS. ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-34-58 REV 15 DTD JAN 2009.</b>					

MOD OUT: 1-3

INSPECTED BY: *Mick White*

REPAIRED BY: **Blackwell, Gary**

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
CUST LABOR R8UAAX1302ZD	OUT OF WARRANTY CHARGE CARD ASSY (A1), MAIN					

**Panasonic SHOP WARRANTY:** All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

\* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty  
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged