



1. Approving Civil Aviation Authority/Country:
FAA/United States

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
20160001757964Y15
324707338

4. Organization Name and Address:
Grimes Aerospace, PSRO
550 State Route 55
Urbana, OH 43078

Repair Station
FQSR015K

5. Work Order/Contract/Invoice Number:
45440864
324707336
Page 1 of 1

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status / Work:
001	CARGO LOAD LT (HALOGEN)	30-2303-15	1	3871	REPAIRED

12. Remarks:
THE SERVICE SPECIFIED HAS BEEN ACCOMPLISHED IN ACCORDANCE WITH:
CMM 33-30-16 Rev 3, MAY/14/2010

THIS DOCUMENT HAS BEEN ISSUED ACCORDING TO AN APPROVED COMPUTER GENERATED SIGNATURE PROCEDURE
MODS: NONE

SEE ATTACHED DOCUMENTS AS APPLICABLE FOR WORK PERFORMED
HONEYWELL CERTIFIES THAT THE WORK SPECIFIED IN BLOCK 11/12 WAS CARRIED OUT IN ACCORDANCE WITH EASA PART 145 AND IN RESPECT TO THAT WORK THE COMPONENT IS CONSIDERED READY FOR RELEASE TO SERVICE UNDER EASA PART 145 APPROVAL NO. EASA 145.4494

<p>13a. Certifies the items identified above were manufactured in conformity to:</p> <p><input type="checkbox"/> Approved design data and are in a condition for safe operation.</p> <p><input type="checkbox"/> Non-approved design data specified in Block 12.</p>	<p>14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12</p> <p>Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.</p>
<p>13b. Authorized Signature:</p>	<p>14b. Authorized Signature: <i>James E Norgrove</i></p>
<p>13c. Approval/Authorization No.:</p>	<p>14c. Approval/Certificate No.: FQSR015K</p>
<p>13d. Name (Typed or Printed):</p>	<p>14d. Name (Typed or Printed): James Norgrove</p>
<p>13e. Date(dd/mm/yyyy):</p>	<p>14e. Date(dd/mm/yyyy): 11/JUL/2016</p>

User / Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1. Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

FAA FORM 8130 - 3 (02-14) NSN : 0052 - 00 - 012 - 9005

SERVICE REPORT

AVIALL SERVICES INC

SR NUMBER: 5009747646		324707338	FAA: FQSR015K	EASA: 145.4494
PO: 45440864	CUSTOMER PART NUMBER:		CONTRACT NUMBER:	
DATE REJECTED: 05/04/2016	DATE RECEIVED: 05/06/2016		DATE COMPLETED: 07/11/2016	
A/C TYPE:	A/C TAIL NUMBER: TBV		A/C SERIAL NUMBER:	
PACKING STATUS: No	SEALS INTACT: Seals None		PHYSICAL DAMAGE: No	
REASON FOR REMOVAL: UNIT REJECTED ON RECEIPT AS ARRIVED WITH LENS, LAMP HOLDER AND REFLECTOR DAMAGED.				
PART NUMBER	AS RECEIVED: 30-2303-15	AS RELEASED: 30-2303-15		
DESCRIPTION:	CARGO LOAD LT (HALOGEN)		CARGO LOAD LT (HALOGEN)	
SERIAL NUMBER	3871	3871		
UID(MFR/SPL SER/UCN PNO)				
HW MOD STATUS:	NONE	NONE		
SW MOD STATUS:				
SOFTWARE LOAD:				
REASON FOR REMOVAL CONFIRMED: Rejection Confirmed			ESTIMATE SUPPLIED: No	
PRIMARY SHOP FINDING: Does Not Apply			WARRANTY: Warranty Accepted	
TYPE OF SERVICE: REPAIRED			TECHNICIAN: John Trego	
MAINTENANCE STATEMENT: PAGE DETAILING WORK PERFORMED, ALONG WITH MATERIALS USED, IS ATTACHED IN PAGE 2.				
SIGNATURE BELOW REQUIRED ONLY WHEN RETURN TO SERVICE IS NOT ISSUED: DATE: _____				
SIGNATURE OF AUTHORIZED PERSON: _____				
Complied With CMM/Eng Documentation: 33-30-16/Rev 3/Rev Date 05/14/2010; Service Bulletins: Customer Manuals/Documentation:				
SHOULD YOU REQUIRE ANY FURTHER INFORMATION REGARDING THIS SERVICE REPORT, OR HAVE ANY QUESTIONS, PLEASE CONTACT OUR CUSTOMER RESPONSE CENTER AT 1-800-601-3099 OR VISIT OUR CUSTOMER PORTAL AT www.MyAerospace.com TO SUBMIT AN				

SERVICE REPORT

AVIAL SERVICES INC

SR NUMBER: 5009747646		FAA: FQSR015K	EASA: 145.4494
PO: 45440864	CUSTOMER PART NUMBER:	CONTRACT NUMBER:	

Previously Complied With
CMM/Eng Documentation:
Service Bulletins:
Customer Manuals/Documentation:

Comments:
UNABLE TO CONFIRM COMMENTS:LENS ASSY IS CRACK.LAMP IS MISSING.
LAMPHOLDER CONTACTS ARE BURNT FROM ARCING.REFLECTOR ASSY IS MARKUP
WITH SCRATCHS.UNIT MAY NEED TOUCHUP PAINT OR PAINTED.
WILL REPAIR TO CMM MANUAL. J.PIDCOCK

E860617 07/11/2016 Repaired and Tested per Listed Documentation.
John Trego

DISPOSITION	REF DSG	P/N Installed	S/N Installed	P/N Removed	S/N Removed	Qty	SB
Replace		LP1987		LP1987		1.000	
Replace		31-7613-1		31-7613-1		1.000	
Replace		31-7789-7		31-7789-7		1.000	
Replace		72605327-1		LH441		1.000	

MEASUREMENT DESCRIPTION	MEAS. VALUE (DECIMAL)	MEAS. VALUE (HH:MM)
Time Since Repair		0:00
Cycles Since Repair		



RTS TECHNICIAN _____

DATE 7-11-16