


1. Approving Civil Aviation Authority/Country
Transport Canada

**AUTHORIZED RELEASE CERTIFICATE
 FORM ONE**

2. Form Tracking Number
WO14956

4. Organization Name and Address:
AJW Technique Inc
 7055, rue Alexander Fleming
 Saint-Laurent QC H4S 2B7
 Canada



5. Work Order, Contract or Invoice Number:
R251429-1

6. Item	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	CIDS DIRECTOR Z011H SERIES	Z011H000241A	1.00	00777	REPAIRED

12. REMARKS
 Unit repaired and tested serviceable in accordance with CMM 23-74-34 Rev. 06
 For details information please see Tear Down/Inspection report.

PRINTED FROM ELECTRONIC FILE

EASA Approval No.: EASA 145.7260
 Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation

Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

CAR 571.10 Maintenance Release

Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number
		<i>B Carle</i>	33-12
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed)	14e. Date (dd/mm/yyyy)
		Benoit Carle	23/Dec/2014

Installer Responsibilities

This certificate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.
 Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

Work Order #: WO14956

Date Printed: 23/12/2014

Customer RO: R251429-1

Page: 1

To:
A J WALTER AVIATION LTD
THE HEADQUARTERS
MAYDWELL AVENUE
SLINFOLD, WEST SUSSEX RH13 0AS
UNITED KINGDOM

Phone #: Code: AJW01 Descr: CIDS DIRECTOR Z011H SERIES	Fax #: PN: Z011H000241A	Serial # : 00777	Email: Qty: 1 Mfg: AIRBUS		
TSN: 0	TSO: 0	TSR: 0	CSN: 0	CSO: 0	CSR: 0

P/N Out: Z011H000241A Serial # out: 00777

Symptoms:

CODE: REASON FOR REMOVAL
DETAILS: Test and recertify.

Faults:

CODE: QUOTE
DETAILS: PRELIMINARY INSPECTION (VISUAL):
PART MISSING: NO
DAMAGE FOUND (CID): NO
HRS/CYCLE RECEIVED: NO

ADDITIONAL REQUIREMENT:

AD, SB, MOD, SIL NO
ADD.CUST. REQUEST NO

WARRANTY REQUESTED? NO

TEST ARRIVAL:

INITIAL TEST FAIL? YES

REASON FOR REMOVAL CONFIRMED: YES

DISASSEMBLY/INSPECTION:

ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION NO

WORK TYPE: REPAIR

WORKSCOPE:

CALIBRATION NO
CLEANING NO
OUT OF SCOPE NO
OVERHAUL NO

Work Order #: WO14956

Date Printed: 23/12/2014

Customer RO: R251429-1

Page: 2

PAINTING NO
PCBR YES
REPAIR YES
REWORK NO
TIME CONTROLLED/TX NO

RE-QUOTE: NO

CODE: INITIAL TEST FAILURE

DETAILS: Initial test failure is attributed to...
- Failed discrete output 33, 34 and 35.

CODE: PCBR

DETAILS: (description, part number or board number).
- Audio Output Board

The following repair
- IC 19, IC20 and IC21 will be replace.

CODE: REPAIR

DETAILS: The following repair(S) will be performed:

- IC 19, IC20 and IC21 will be replace on the Audio Output Board
- Final test will be perform after re-assembly.

Corrective Actions:

CODE: REPAIRED

DETAILS: IC 19, IC20 and IC21 replaced on the Audio Output Board.
Unit tested serviceable in accordance with CMM 23-74-34 Rev.06

<i>PN</i>	<i>Description</i>	<i>Reason</i>	<i>Qty Needed</i>	<i>CD</i>	<i>Disposition</i>
TDE1798DP	ESDS IC19-21 IC	DE	3	NE	Consumable