

61360475

1. Approving Competent Authority / Country LBA / Germany		2. AUTHORISED RELEASE CERTIFICATE EASA FORM 1		3. Form Tracking Number 19425494 00000001	
4. Organisation Name and Address: Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany					
6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
01	HANDHELD MICROPHONE		1	33649	REPAIRED
12. Remarks ATA 2351 TP R MK-No. 13 Pack Code 00 Resp. Workshop 32322022 Workshop Station FRA025 WIZZ Air Hungary Kft. R5799417					
<p>airberlin TRUE COPY</p> <p>Return to Service in Accordance with 14 CFR part 43 The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work the items are approved for return to service under</p> <p>FAA Certificate No. DLAY225D TCCA Approval No. 897-08</p>					
13a. Certifies that the items identified above were manufactured in conformity to: <input type="checkbox"/> approved design data and are in a condition for safe operation <input checked="" type="checkbox"/> Part-145.A.50 Release to Service <input checked="" type="checkbox"/> Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part- 145 and in respect to that work the items are considered ready for release to service. <input type="checkbox"/> non-approved design data specified in block 12 Further details of work performed are attached either in a Workshop Report (reference number: see blocks 3 and 5) or in other applicable documents.					
13b. Authorised Signature		13c. Approval / Authorisation Number		14c. Certificate / Approval Ref. Number	
				DE.145.0001	
13d. Name		13e. Date (dd mmm yyyy)		14e. Date (dd mmm yyyy)	
				27 Jul 2017	

EASA FORM 1 - Issue 2
USER/INSTALLER RESPONSIBILITIES

Note: This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different from the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.



Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



61360475

Certificate Ref. No.	19425494 00000001
Work Order/Contract/Invoice	61360475
Description	HANDHELD MICROPHONE
Responsible Workshop	32322022
Modification Status according to Mod-Label	See Unit Mod-Label if equipped
Name	52955, Anja-Elisabeth Irle
Date (dd mmm yyyy)	27 Jul 2017

Workshop Report

Customer Order No. R5799417	 Lufthansa Technik Lufthansa Technik AG Weg beim Jäger 193 22335 Hamburg Germany
Part No. as received M83/P1801A	Serial No. as received 33649
Part No. as dispatched M83/P1801A	Serial No. as dispatched 33649
Reason for removal Intermittent failure.	
Findings Cap., rear and grommet broken.	
Action New cap, rear and grommet installed. Unit passed testing procedure in accordance to applicable maintenance documents. All measurements within required limits.	
	
The work specified above has been performed subject to Lufthansa Technik's Standard conditions for Technical Services which, if not superseded by another agreement or not yet agreed upon before, are acknowledged by the customer with acceptance of the part(s) hereunder.	