

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
R330542

5. Work Order/Contract/Invoice Number:
9159

2. Approving Civil Aviation Authority/Country:
FAA/UNITED STATES

4. Organization Name and Address:
Repair Station# J30R252Y
JJA AVIATION INC.
3468 W 84th St Bay.106, Hialeah FL 33018, Fax : 786/558-4622, 305/498-7920

6.Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	CONTACTOR	ELM832-1	1	CL-69242	REPAIRED

12. Remarks: **REPAIRED IN ACCORDANCE WITH CMM 24-09-51 REV.4 DATED DEC 3,2008**
FULL DETAILS OF WORK CARRIED OUT PER WORK ORDER NO. : 9159

Certifies that the work specified in block 11/12 was carried out in accordance with EASA 145 and with respect to that work the aircraft component is considered ready to release to service under EASA Acceptance Certificate Number: **145.5947**


13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in condition for safe operation.

Non-approved design data specified in Block 12.

14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 13

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:	13c. Approval/Authorization No.:	14c. Approval/Certificate No.:	14e. Date (dd/mm/yyyy):
		J30R252Y	12 / Jan / 2018
13d. Name (Typed or Printed)	13e. Date (dd/mm/yyyy):	14b. Authorized Signature:	14d. Name: (Typed or Printed)
			GIONARYS CASARREAL

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



WORK ORDER



JJA AVIATION INC.

3468 W 84th St Bay.106
Hialeah FL 33018
Phone: 305/498-7920
Fax : 786/558-4622
FAA CRS No : J30R252 / EASA.145.5947

WO : 9159-17

Customer : AJW001 / AJ WALTER AVIATION LTD

Outg. P/N : ELM832-1 / CONTACTOR

Manufact.: HARTMAN

Dept. : ACC

Cust RO : R330542

Outg. S/N : CL-69242

Warranty : 00 / 365

Goodthru AD# :

Manual#: MN-1167 ATA: 24-09-51 Rev#: 4 RevDate:Dec 3,2008 Revised Date:Dec 7,2017

Assets:

Incoming P/N: ELM832-1

Incoming S/N: CL-69242

Incoming Work Req: BC

Outgoing Work Req: REPAIR

Reason/Rm:

R X RABBAN BUS DOES NOT POWER

Date Recvd: Dec 7,2017

Date Reqr'd: Jan 10,2018

Date Estmtd: Dec 12,2017

PRELIMINARY INSPECTION:

DATE: Dec 18,2017

INSPECTOR: JCA

VERIFIED PART NUMBER AND SERIAL NUMBER.

UNIT RECEIVED IN FAIR CONDITION.

PRE TEST (Yes/No): Y

DATE: Dec 18,2017

INSPECTOR: JCA

UNIT FAILED FUNCTIONAL TEST.

UNIT INOPERATIVE.

HIDDEN DAMAGE:

N/A

TEARDOWN FINDINGS:

OPENED UNIT AS REQUIRED FOR INSPECTION AND TROUBLESHOOTING. INSPECTION REVEALED EXTERNAL SLIGHT DUST CONTAMINATION. TROUBLESHOOTING REVEALED DEFECTIVE ACTUATOR ASSEMBLY DUE TO NORMAL WEAR AND TEAR CAUSING UNIT TO BE INOPERATIVE.

UNIT REQUIRES CLEANING AND REPAIR.

TECHNICIAN: LEG

DATE: Dec 18,2017

INSPECTOR: JCA

FINAL INSPECTION BEFORE ASSEMBLY:

DATE: Jan 12,2018

INSPECTOR: GXC

CORRECTIVE ACTION:

CLEANED, INSPECTED, REPLACED DEFECTIVE PART MENTIONED ON TEARDOWN FINDING, REPAIRED AND FUNCTIONALLY TESTED UNIT I/A/W MFG SPEC'S.

TECHNICIAN: LEG

DATE: Jan 12,2018

INSPECTOR: GXC

MODIFICATION/SERVICE BULLETINS:

NO S/B INSTALLED AND N/A AD'S.

Test Data Used: ATA# 24-09-51 REV# 4 DATED: 12-03-2008

Test Technician: LEG

DATE: Jan 12,2018

Inspector: GXC

DATE: Jan 12,2018

Labor Task Control#





WORK ORDER



JJA AVIATION INC.

3468 W 84th St Bay.106
Hialeah FL 33018
Phone: 305/498-7920
Fax : 786/558-4622
FAA CRS No : J30R252 / EASA.145.5947

WO : 9159-17

Customer : AJW001 / AJ WALTER AVIATION LTD
Outg. P/N : ELM832-1 / CONTACTOR
Manufact.: HARTMAN
Dept. : ACC

Cust RO : R330542
Outg. S/N : CL-69242
Warranty : 00 / 365
Goodthru AD# :

Final Inspection:GXC

DATE: Jan 12,2018

ADDITIONAL COMMENTS:

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved return to Service By GIONARYS CASARREAL

Date Jan 12,2018

Labor Task Control#

