

2. AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

1. Approving Competent Authority / Country
CIVIL AVIATION AUTHORITY
United Kingdom

3. Form Tracking Number
BA33049495

4. Organisation Name and Address
BRITISH AIRWAYS
British Airways Avionics Engineering.
Ely Meadow, Talbot Green,
Pontyclun, Cardiff CF72 8XL

5. Work Order/Contract/Invoice
4521031
R328369

6. Item	7. Description	8. Part number	9. Qty	10. Serial No.	11. Status/Work
1.	FULL AUTHORITY FUEL CTRL	FAPC2000-12BK6	1	BX53790	Repaired

12. REMARKS : Batch No 0005877310
S/N BX53790. Passed pretest. D07, D08 pcbs inspected for solder spread
law SB FAPC2000-73-110. D12 pcbs inspected for corrosion. Temperature
labels fitted to top cover. A/V mounts replaced. Passed final test. ATP
2422 Rev 16B. CMM: ATA 73-21-09 Rev 16, date of Revision 17Mar2014.

13a. Certifies that the items identified above were manufactured in conformity to:
 approved design data and are in condition for safe operation
 non-approved design data specified in block 12

14a. PART-145.A.50 Release to service Other Regulation specified in block 12
Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with PART 145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature
13c. Approval/Authorisation Number
13d. Name
13e. Date (dd/mm/yyyy)

14b. Authorised Signature
14c. Certificate/Approval Ref. no.
14d. Name
14e. Date (dd/mm/yyyy)

14c. Certificate/Approval Ref. no.
UK.145.00142

14e. Date (dd/mm/yyyy) 29.Nov.2017

14d. Name U724669
Brian Farmer BAAE 206 CRS

USER/INSTALLER RESPONSIBILITIES
This certificate does not automatically constitute authority to install the item(s).
Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

Component Strip Report

Customer: AJW AVIATION

The Headquarters, Maydwell Avenue
Slinfold, West Sussex
RH13 0AS

Part Number: FAFC2000-12BK6:K0131

Serial Number: BX53790

Description: FULL AUTHORITY FUEL CTRL

Repair Order Number: R328369

Order Number: 4521031

Equipment Number: 42064936

Batch Number: 0005877310

Warranty Requested:

Customer WORK REQUIRED :

Date of Receipt: 19.10.2017

Reason for Removal:

Removal Code: W465 FE

Reason for removal: DURING ENG START ENG #4 EICAS MESSAGE "AUTO START"

Date Serviceable: 29.11.2017

S/N BX53790. Passed pretest. D07, D08 pcbs inspected for solder spread
iaw SB FAFC2000-73-110. D12 pcbs inspected for corrosion. Temperature
labels fitted to top cover. A/V mounts replaced. Passed final test. ATP
2422 Rev 16B. CMM: ATA 73-21-09 Rev 16, date of Revision 17Mar2014.

Warranty Decision:

Tested

Repaired

Overhauled

Inspected

Re-manufactured

New

Modified

Certification Number: BA000033049495