

1. Approving Competent Authority / Country: **United Kingdom** 2 **AUTHORISED RELEASE CERTIFICATE** 3. Form Tracking Number: **L 2596723**  
**Civil Aviation Authority**


4. Organization Name and Address: **Panasonic** 5. Work Order/Contract/Invoice **R286218**  
**Panasonic Avionics Corporation**  
 Quadrant House, Heron Drive, Parfaint Road, Langley Berks, SL3 8XP, UK

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No	11. Status / Work
1	ANNOUNCEMENT CONTROL UNIT	RD-AX7201	1	100237	REPAIRED

12. Remarks PLEASE REFER TO SR NUMBER 4280528.

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service: UZVY163X. In accordance with TCCA Approval 808-03.  
 Panasonic Avionics Corporation internal reference **SR4280528**

13a. Certifies the items identified above were manufactured in conformity to  
 approved design data and are in a condition for safe operation.  
 non-approved design data specified in block 12.  
 14a.  PART 145.A.50 Release to Service  Other regulation specified in block 12  
 Certifies that unless otherwise specified in Block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature:	13c. Approval/Authorization Number	14b. Authorized Signature:	14c. Certificate/Approval Ref No:
			<b>UK.145.00297</b>
13d. Name	13e. Date (dd mmm yyyy)	14d. Name	14e. Date (dd mmm yyyy)
		Mick White	16-MAR-2016



USER/INSTALLER RESPONSIBILITIES  
 This certificate does not automatically constitute authority to install the item(s).  
 Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.  
 Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Panasonic Avionics Corporation

Quadrant House, Heron Drive, Parlaunt Road, Langley Berks, SL3 8XP, UK.

Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

REPAIR REPORT / DELIVERY ORDER

SOLD TO AJ WALTER AVIATION THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, ENGLAND RH13 0AS, GB

SHIP TO AJ WALTER AVIATION THE HEADQUARTERS MAYDWELL AVENUE SLINFOLD, ENGLAND RH13 0AS, GB

PAGE 1 of 1

SHIP TRANSACTION:



Table with customer and part details: CUSTOMER P.O. NUMBER R286218, PART NUMBER RD-AX7201, Nomenclature ANNOUNCEMENT CONTROL UNIT, SERIAL NUMBER 100237, DATE OF MFG 28-FEB-1989, WTY START DATE 28-FEB-1989, WTY END DATE 30-MAY-1992, DATE REPAIRED 11-MAR-2016, SHIP DATE 26-FEB-2016. Includes internal and external inspection notes and a detailed failure/corrective action report.

MOD OUT: 1-6,8

INSPECTED BY: Mick White

REPAIRED BY: Binning, Gavin Douglas

Table with 7 columns: PART NUMBER, DESCRIPTION, QTY, UNIT PRICE, EXTENDED PRICE, CHARGED AMOUNT, WTY\*. Lists various parts like R8C12X7001, R6DE10A, R6HM118B, etc.

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

Summary table: Cost of Labor 1,020.00, Cost of Material 337.86, Total Cost 1,357.86

\* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged