

1. Approving Competent Aviation Authority / Country: **2**
United Kingdom
Civil Aviation Authority

AUTHORISED RELEASE CERTIFICATE
EASA FORM 1

3. Form Tracking Number:
L 2321330



4. Organisation Name and Address:
Panasonic
Panasonic Avionics Corporation
 Quadrant House, Heron Drive, Parlaunt Road, Langley Berks, SL3 8XP, UK

5. Work Order/Contract/Invoice
U10456

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status / Work
1	9-IN LCD CEILING MOUNT INST	RD-AA902125-01	1	100006	REPAIRED

12. Remarks **INNER UNIT RD-AV9811-01 S.N. 100006 CONFORMED IAW CMM 23-32-58 REV 27 DTD SEP 2014. LRU CONFORMED IAW CMM 23-09-90 REV 14 DTD SEP 2014.**

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service. UZVY163X.
 Panasonic Avionics Corporation Internal reference SR 3797374

13a. Certifies the items identified above were manufactured in conformity to: <input checked="" type="checkbox"/> approved design data and are in a condition for safe operation. <input type="checkbox"/> non-approved design data specified in block 12.		14a. <input checked="" type="checkbox"/> PART 145.A.50 Release to Service <input checked="" type="checkbox"/> Other regulation specified in block 12
13b. Authorised Signature	13c. Approval/Authorisation Number	14b. Authorised Signature: 
13d. Name	13e. Date (dd mmm yyyy)	14c. Certificate/Approval reference No: UK.145.00297
		14d. Name Mick White 
		14e. Date (dd mmm yyyy) 14-NOV-2014

USER/INSTALLER RESPONSIBILITIES

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Panasonic Avionics Corporation

Quadrant House, Heron Drive, Parlaunt Road,
Langley Berks, SL3 8XP, UK.

Tel: +44(0) 1753 741450 Fax: +44(0) 1753 741481

REPAIR REPORT / DELIVERY ORDER

SOLD TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SINFOLD, ENGLAND RH13 0AS, GB

SHIP TO AJ WALTER AVIATION
THE HEADQUARTERS
MAYDWELL AVENUE
SINFOLD, ENGLAND RH13 0AS, GB



PAGE 1 of 1

SHIP TRANSACTION:

CUSTOMER P.O. NUMBER U10456		CUSTOMER 1001	TAIL NO. SPARES	CUST PROD REF 309474	SERVICE REQUEST 3797374	
PART NUMBER RD-AA902125-01		NOMENCLATURE 9-IN LCD CEILING MOUNT INSTL			DATE REMOVED	DATE RECEIVED 07-NOV-2014
SERIAL NUMBER 100006		DATE OF MFG 28-FEB-1997	WTY START DATE 28-FEB-1997	WTY END DATE 30-MAY-2000	DATE REPAIRED 12-NOV-2014	SHIP DATE
MOD IN 1-5						
REASON FOR CUSTOMER REJECTION	PLEASE TEST AND RECERT.					
INTERNAL INSPECTION	No Physical Damage - DIRTY.					
EXTERNAL INSPECTION	No Physical Damage - DIRTY.					
ACTUAL FAILURE / CORRECTIVE ACTION	NO REPORTED FAILURE. MEC ASSY TORQUE TOO HIGH; READJUSTED. UNIT CLEANED AND TESTED, PASSED FUNCTIONAL TESTS.ALL WORK HAS BEEN CARRIED OUT AND LRU CONFORMED IAW CMM 23-09-90 REV 14 DTD SEP 2014.					

MOD OUT: 1-5

INSPECTED BY: **Mick White**

REPAIRED BY: **ELPHICK, NEIL**

PART NUMBER	DESCRIPTION	QTY	UNIT PRICE	EXTENDED PRICE	CHARGED AMOUNT	WTY*
CUST LABOR	OUT OF WARRANTY CHARGE	420				

Panasonic SHOP WARRANTY: All repairs referenced by this Repair Report are warranted as to parts and labor for a period of 12 months from the date of such repair. Used serviceable components may have been used in restoring this unit.

Cost of Labor
Cost of Material

* WTY CODES NO = Not Covered FOC = SB covers as FOC SHOP = Shop Wty
WARR = Mfg Wty in Effect FIXED = Fixed Price Repair CC = Panasonic Charged

Total Cost