

1. Approving Competent Authority / Country  
**LUFTFAHRT-BUNDESAMT**  
 Germany

2. **AUTHORISED RELEASE CERTIFICATE**  
**EASA FORM 1**

3. Form Tracking Number  
**DB 90590487 1/1**

4. Organisation Name and Address:  
**AIRBUS**  
 AIRBUS Operations GmbH  
 Lüneburger Schanze 30  
 21614 Buxtehude, Germany

5. Work Order/Contract/Invoice  
**R330876**

6. Item	7. Description	8. Part No.	9. Qty	10. Serial-No.	11. Status/Work
N/A	CIDS DEU TYPE B	Z040H0003110	1	040H0000185	INSPECTED TESTED

12. Remarks: see Maintenance Report No.1039883  
 Work performed as per: C.M.M. 23-73-47 Rev.12 Feb-22-2016.  
 work accomplished: DEC-12-2017

The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. K30Y905Y.

13a. Certifies that the items identified above were manufactured in conformity with:

approved design data and was in a condition for safe operation

non-approved design data specified in block 12

13b. Authorised Signature: \_\_\_\_\_

13c. Approval/Authorisation Number: \_\_\_\_\_

13d. Name: \_\_\_\_\_

13e. Date (dd/mm/yyyy): \_\_\_\_\_

14a.  Part-145.A.50 Release to Service  Other Regulation specified in block 12


14b. Authorised Signature: *Zeigermann*


14c. Certificate/Approval Ref.No.: **DE.145.0286**

14d. Name: **Zeigermann**

14e. Date (dd/mm/yyyy): **15.Dec.2017**

USER / INSTALLER RESPONSIBILITIES  
 This certificate does not automatically constitute authority to install the items.  
 Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.  
 Statements in blocks 13a and 14g do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.  
 EASA-Form 1 - MF/145 Issue 21  
 BXP-MD100

<b>MAINTENANCE ORDER</b>		<b>V</b> Activity Category		<b>1039883</b> Maintenance Number			 FSCM C9072	
Customer <b>AJW</b>		Part Number <b>Z040H0003110</b>			Serial No SPEC2000 <b>040H00000185</b>		Amd.	
		Description <b>CIDS DEU TYPE B</b>			Quantity <b>1</b>		Repair-Station <b>BUX</b>	
Customer Order <b>R330876</b>		Cust. Order Date <b>27.11.2017</b>		Work Order <b>1039883</b>		Work Order Date <b>30.11.2017</b>		Prio <b>ROUTINE</b>
Required Activities:	Test <b>X</b>	Repair <b>X</b>	Modify	Inspection <b>X</b>	Scrap	Overhaul	Entry Date <b>30.11.2017</b>	Redelivery Date <b>06.12.2017</b>
Reason for Return <b>Please test and recert</b>								
Operator <b>UKN</b>		Removal Date	AC-Reg <b>F-GZZZ</b>	AC Type <b>A320</b>	Station <b>UKN</b>	Release Certificate <b>EASA DUALFAA</b>	Warranty	Chargeable <b>X</b>
		Operators Man		OEM-Man <b>O.E.M.-M</b>	Aviation Device <b>YES</b>		Package <b>OK</b>	
Administrator: <b>Sell</b>			Department: <b>ECYS1</b>			Phone: <b>040 743 51261</b>		

<b>MAINTENANCE REPORT</b>		Preliminary Inspection/HDI	Pre- Strip-Test <b>YES</b>	Cond. elec. <b>OK</b>	Cond. SW <b>N/A</b>	Cond. mech. <b>OK</b>	BITE <b>N/A</b>
		Status of Removal <b>Unjustified Removal</b>		Tech. warranty <b>YES</b>		Missing Part <b>NO</b>	
Findings: <b>No error detected.</b>							
Remarks: <b>Work performed as per: C.M.M. 23-73-47 Rev.12 Feb-22-2016.</b>							
Work performed: <b>Preliminary- and hidden damage inspection performed. Acceptance test successfully performed.</b>							
							
Final Condition		PN_After <b>Z040H0003110</b>		SN_After <b>040H00000185</b>		AMD_After	
		Tested <b>X</b>	Repaired	Modified	Modified internal	Cond as is	Scrapped
		Warranty_Charge_WC <b>C</b>		NFF		QA-Inspected	
Work performed staff <b>Sperhake</b>		Work performed department <b>ECYS3</b>		Work performed date <b>12.12.2017</b>		<b>15. Dez. 2017</b> 