

1. Approving Civil Aviation Authority/Country:

FA/UNITED STATES

AUTHORIZED RELEASE CERTIFICATE

FAA FORM 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
FWO10112

4. Organization Name and Address:

1ST Choice Aerospace
3361 Enterprise Way, Miramar, FL. 33025, Fax:954/430-6601, 954/430-6600

Repair Station: 9QAR940B

5. Work Order/Contract/Invoice Number:
FWO10112 / R378109

6. Item

1

7. Description:

POS IND ACCY UNIT

8. Part Number:

65-52807-39

9. Quantity:

1.00

10. Serial Number:

D01264

11. Status/Work:

REPAIRED

12. Remarks: This item was REPAIRED I/AV Manual # CMM 27-56-40, Revision # 45 Revision Date 1/19/2012

NO APPLICABLE AD'S AND NO SB'S INSTALLED.

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release to service under EASA Part 145 Approval no. EASA.145.6610

14a. 14 CFR 43.9 Return to Service

Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

14b. Authorized Signature:

14c. Approval/Certificate No.:

9QAR940B

14d. Name (Typed or Printed):

RAUL A DALEY

14e. Date (dd/mm/yyyy):

08-Dec-2020

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1. It is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statement in Blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

WORK ORDER FORM 100

Page No. 1

1st Choice Aerospace

3361 Enterprise Way
Miramar, FL 33025
Fax: 954/430-6601
954/430-6600

**FAA CRS No: 9QAR940B****Work Order #: FWO10112**

Step: SH-SHIPPING

Department: Shop FLA

Location: FLA ACC

Customer: **FAJW001 / AJ WALTER AVIATION**Cust RO#: **R378109**Mfg: **BAE*******NO PMA PARTS*****

Warranty Code: 00

Outgoing: **65-52807-39 / POS IND ACCY UNIT**

S/N: D01264

Goodthru AD#:

Incoming P/N: 65-52807-39

Incoming S/N: D01264

Incoming work Req: RE

Outgoing Work Req: REPAIRED

Repair Manuals: F0950

RevDate: 1/19/2012

Rev#: 45

ATA: 27-56-40

Tools:**REASON FOR REMOVAL** Date Recvd: 10/7/2020 Date Reqrd 10/20/2020 Date Estmtd: 10/20/2020RFR: DEVISE ANNUNCIATOR WITH SLAT #1, INDICATES FULL EXTEND.
LEADING EDGE FLAP SLAT POSITION LIGHT SYSTEMS.

PLEASE REPAIR UNDER T&M - QUOTE AND HOLD.

PRELIMINARY INSPECTION: DATE: 10/12/2020 INSPECTOR: EXG

VERIFIED P/N AND S/N ON ID PLATE AND R/O. UNIT RECEIVED IN FAIR CONDITION.

PRE TEST (Yes/No): Y DATE: 10/12/2020 INSPECTOR: EXG

UNIT FAILED FUNCTIONAL TEST. REASON FOR REMOVAL CONFIRMED.

HIDDEN DAMAGE:

N/A

TEARDOWN FINDINGS:OPENED UNIT AS REQUIRED FOR INSPECTION AND TROUBLESHOOTING. VERIFIED REPORTED DISCREPANCY.
TROUBLESHOOTING SHOWS DEFECTIVE A2 PRINTED CIRCUIT ASSEMBLY, PROXIMITY SWITCH IS ADDITIONAL
TROUBLE FOUND. UNIT QUOTE FOR REPAIR.

REPAIR QUOTE.

TECHNICIAN: RDS DATE: 10/12/2020 INSPECTOR: EXG

FINAL INSPECTION BEFORE ASSEMBLY DATE: 12/08/20 INSPECTOR: RAD**CORRECTIVE ACTION:**THIS UNIT WAS DISASSEMBLED, CLEANED, INSPECTED,
REPAIRED AS NECESSARY, REASSEMBLED, AND FUNCTIONALLY
TESTED IN ACCORDANCE WITH MANUFACTURER'S SPECIFICATIONS.

TECHNICIAN: RDS DATE: 12/08/20 INSPECTOR: RAD

MODIFICATION/SERVICE BULLETINS:

NO APPLICABLE AD'S AND NO SB'S INSTALLED.

TEST DATA USED:

ATA: 27-56-40 REV#45 19JAN2012

WORK ORDER FORM 100

1st Choice Aerospace

3361 Enterprise Way
Miramar, FL. 33025
Fax: 954/430-6601
954/430-6600



FAA CRS No: 9QAR940B

Work Order #: FWO10112

Step: SH-SHIPPING

Department: Shop FLA

Location: FLA ACC

Customer: **FAJW001 / AJ WALTER AVIATION**

Cust RO#: **R378109**

Mfg: **BAE**

*****NO PMA PARTS*****

Warranty Code: 00

Outgoing: **65-52807-39 / POS IND ACCY UNIT**

S/N: D01264

Goodthru AD#:

Incoming P/N: 65-52807-39

Incoming S/N: D01264

Incoming work Req: RE

Outgoing Work Req: REPAIRED

Test Technician: RDS

Date: 12/08/20

Final Inspection: RAD

Date: 12/08/20

ADDITIONAL COMMENTS:

N/A

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by **RAUL A DALEY**



Date: 12/8/2020 12:36:36 PM