

1. Approving Competent Authority/Country  
**CA/UNITED KINGDOM**

## AUTHORISED RELEASE CERTIFICATE EASA FORM 1

3. Form Tracking Number.  
**131230**

4. Organisation Name and Address.

**MUIRHEAD AEROSPACE LIMITED  
 T/A MUIRHEAD AVIONICS  
 Muirhead Aerospace Ltd  
 3 The Square Heathrow  
 Southall Lane, Southall, Middlesex  
 UB2 5NH  
 UNITED KINGDOM**

5. Work Order/Contract/Invoice

**Work Order No: RA13669  
 Customer Order No: R249984**

6. Item	7. Description	8. Part No.	9. Qty.	10. Serial No.	11. Status/Work
1	DME INTERROGATOR	2041167-3709	1	2772	Inspected/Work

12. Remarks

Manual ID: IB1137A-1, Revision #: 08, Revision Date: 21/10/2013

14 CFR 43.9 Return to Service

The work identified in Block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. H9EY443N

Date(m/d/y): Dec/08/2014

Signed:

Repair report attached reference RA13669  
 TCCA Approval Ref: 807-07

*[Signature]*  


13a. Certifies that the items identified above were manufactured in conformity to:

- approved design data and are in a condition for safe operation.
- non-approved design data specified in block 12

14a.  Part-145.A.50 Release to Service  Other regulation specified in Block 12

Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.

13b. Authorised Signature:

13c. Approval/Authorisation No.

14b. Authorised Signature


14c. Certificate/Approval Ref No.

13d. Name

13e. Date (dd mmm yyyy)

14d. Name

14e. Date (dd mmm yyyy)

*[Signature]*  


*[Signature]*

**USER/INSTALLER RESPONSIBILITIES**

This certificate does not automatically constitute authority to install the item(s).

Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.

Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



Muirhead Aerospace Limited

Contact Name: Customer Services  
Telephone: +44 (0)20 8571 3422  
Fax: +44 (0)20 8571 2336

Tear Down/Inspection

Work Order #: RA13669

Date Printed: 28-Nov-14

Work Type: Repaired

Page: 1

To:  
ATTN: Progressing  
AJ WALTER (AVIATION) LTD  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD  
WEST SUSSEX RH13 0SH

Ship To:  
AJ WALTER (AVIATION) LTD  
THE HEADQUARTERS  
MAYDWELL AVENUE  
SLINFOLD  
WEST SUSSEX, RH13 0SH UNITED KINGDOM

Cust.PO Ref.: R249984  
Cust.Code: 203205

Cust.Phone:  
Cust.Fax:

Cust.Email: stockmarket@ajw-aviation.com  
Station: SOUTH

Part No. In: 2041167-3709

Description: DME INTERROGATOR

Qty: 1

Part No. Out: 2041167-3709

Serial No: 2772

Previous WO No:

TSO: 0

TSN: 0

TSR: 0

CSO: 0

CSN: 0

CSR: 0

Documentation: IB1137A-1  
ATA No: 34-51-34

Location:  
Rev. & Date: 08 21-Oct-2013

Symptoms:

REPORT

REASON FOR REMOVAL:- UNKNOWN.

UNIT INSPECTED AND FULLY TESTED I.A.W. THE MANUFACTURER'S SPECIFICATION AND IS FOUND TO BE OPERATING SATISFACTORILY.

Inspection Signature:










Stamp:

Inspect. Print Name:

P S SHAWZALE

Job No: <b>RA13669</b>	<b>Work Order Scope and Traveller</b> <b>Muirhead Aerospace Limited</b>	Date Printed: 28-Nov-14 Time: 8:47:51 AM Page: 1 of 1
Part No: 2041167-3709	Description: DME INTERROGATOR	Qty: 1 Serial No: 2772
Cust Code: 203205	Customer Name: AJ WALTER (AVIATION) LTD	Cust Ref No: R249984
OEM: HONEYWELL	Date In: 21-Nov-14	Due Date: 01-Dec-14 Scheduled Date:
Documentation Used: IB1137A-1	ATA#: 34-51-34	Rev#: 08 21-Oct-2013

Task: **WORK CARRIED OUT** Est. Time: 0 Sequence: 1

OP	Description	D.O.M.	Tech.	Signature
OP1.	Visual Inspection: SATIS	N/A	<input checked="" type="checkbox"/>	
OP2.	Functional Test: SATIS	Reported Defect Confirmed Yes [ ] No [ ]	<input checked="" type="checkbox"/>	
OP3.	Malfunction Cause and Corrective Action: UNIT BENCH CHECKED AND APPEARS TO OPERATE SATISFACTORILY. UNIT SOAK TESTED SEVERAL HOURS - NO FAULT FOUND PARAMETERS CHECKED - SATIS BOARD EDGE CONNECTORS CLEANED AS A PRECAUTION. UNIT TESTED TO SPEC		<input checked="" type="checkbox"/>	
			<input checked="" type="checkbox"/>	
			<input checked="" type="checkbox"/>	
			<input checked="" type="checkbox"/>	
			<input checked="" type="checkbox"/>	
			<input checked="" type="checkbox"/>	
OP4.	Mods / SBs / ADs Embodied: N/A		<input checked="" type="checkbox"/>	
OP5.	Final Inspection and Test: Inspected By: <i>[Signature]</i> Date: 28 Nov 2014	Overhauled: [ ] Modified: [ ] Calibrated: [ ]	Repaired: [ ] Inspected/Tested: [X] Readout: [ ]	Final Insp. 