

AUTHORISED RELEASE CERTIFICATE

EASA FORM 1

1. Approving Competent Authority / Country LUFTFAHRT-BUNDESAMT Germany	2.	3. Form Tracking Number DB 90582178 1/1
--	----	---

4. Organisation Name and Address: <p style="text-align: center;">AIRBUS</p> AIRBUS Operations GmbH Lüneburger Schanze 30 21614 Buxtehude, Germany	5. Work Order/Contract/Invoice <p style="text-align: center;">R327678</p>
---	---

6. Item	7. Description	8. Part No.	9. Qty	10. Serial-No.	11. Status/Work
N/A	FAP LIGHT PANEL	Z150H00068110	1	150H00001296	INSPECTED TESTED

12. Remarks: see Maintenance Report No.1038859
 Work performed as per: CMM 23-73-10 Rev. 02 APR-04-2017.
 Work accomplished: OCT-13-2017
 Amendment:A

The work identified in block 11 and described herein has been accomplished in accordance with 14 CFR part 43 and in respect to that work, the items are approved for return to service under certificate no. K30Y905Y.

13a Certifies that the items identified above were manufactured in conformity to: <ul style="list-style-type: none"> <input type="checkbox"/> approved design data and are in a condition for safe operation <input type="checkbox"/> non-approved design data specified in block 12 	14a. <input checked="" type="checkbox"/> Part-145.A.50 Release to Service <input checked="" type="checkbox"/> Other Regulation specified in block 12 Certifies that unless otherwise specified in block 12, the work identified in block 11 and described in block 12, was accomplished in accordance with Part-145 and in respect to that work the items are considered ready for release to service.
13b. Authorised Signature:	14b. Authorised Signature:
13c. Approver/Authorisation Number:	14c. Certificate/Approval Ref.No.: DE.145.0286
13d. Name:	14d. Name: Heymann
13e. Date (dd/mm/yyyy):	14e. Date (dd/mm/yyyy): 20.Oct.2017

USER / INSTALLER RESPONSIBILITIES
 This certificate does not automatically constitute authority to install the item(s).
 Where the user/installer performs work in accordance with regulations of an airworthiness authority different than the airworthiness authority specified in block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts items from the airworthiness authority specified in block 1.
 Statements in blocks 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

EASA-Form 1 - MF/145 Issue 2] BXP-MD100

1 国家 Country China	2. 中国民用航空总局 CAAC <input type="checkbox"/> 符合性 Conformity <input checked="" type="checkbox"/> 适航性 Airworthiness	3 证书编号 Certificate Ref. No.
批准放行证书/适航批准标签 AUTHORIZED RELEASE CERTIFICATE/AIRWORTHINESS APPROVAL TAG		DB 90582177

4 单位 Organization AIRBUS	AIRBUS Operations GmbH Lüneburger Schanze 30 21614 Buxtehude, Germany Plant Werk Buxtehude	5 工作单/合同单/货单 Work Order/Contract/Invoice R327678
------------------------------------	---	--

6 序号 Item	7 内容 Description	8 件号 Part No.	9 适用性 Eligibility	10 数量 Qty	11 系列号/批号 Serial/Batch No.	12 产品状态 Status/Work
0001	FAP LIGHT PANEL	Z150H0068110	APPLICABLE TO MULTIPLE TYPES	1	150H00001296	INSPECTED TESTED


13 备注 Remarks
see Maintenance Report No.1038859 Work performed as per: CMM 23-73-10 Rev. 02 APR-04-2017. work accomplished: OCT-13-2017 Amendment:A



14 新产品 New Parts
 兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例进行制造/检查，并且该
 产品（出口产品）符合经批准的型号或材料进口国提出的专门要求。
 Certifies that the Part(s) identified above except as otherwise specified in block 13
 was(were) manufactured/inspected in accordance with the airworthiness regulations of
 the stated country and/or in the case of parts to be exported with the approved design
 data and with the notified special requirements of the importing country.

15 使用过的产品 Used Parts
 兹声明上述产品除第13项的其它规定以外，已按照上述国家适航条例和进口国
 通知的特殊要求进行工作，该产品处于安全可用状态可以批准放行使用。
 Certifies that the work specified above except as specified in block 13 was carried out
 in accordance with the airworthiness regulations of the stated country and the notified
 special requirements of the importing country and in respect to that work, the part(s) is
 (are) in condition for safe operation and considered ready for release to service. (over)

16 批准人签名 Signature 	18 批准日期 Date 20.Oct.2017	19 中国民航总局授权 Issued by or on behalf of the CAAC
17 批准人姓名 (打印的) Name(Printed) Heymann DA_K_50		F04900446

*参阅产品目录详细查找适用性
 Cross-check eligibility for more details with parts catalogue

MAINTENANCE ORDER		V Activity Category		1038859 Maintenance Number			 FSCM C9072	
Customer AJW		Part Number Z150H0068110			Serial No SPEC2000 150H00001296		Amd. A	
		Description FAP LIGHT PANEL			Quantity 1		Repair-Station BUX	
Customer Order R327678		Cust. Order Date 03.10.2017		Work Order 1038859		Work Order Date 05.10.2017		Prio ROUTINE
Required Activities:	Test X	Repair	Modify	Inspection X	Scrap	Overhaul	Entry Date 05.10.2017	Redelivery Date 11.10.2017
Reason for Return History of Faults for Repair								
Operator UKN		Removal Date 23.09.2017	AC-Reg LY-SPF	AC Type A320	Station UKN	Release Certificate AAC038/EDUAL	Warranty	Chargeable X
		Operators Man		OEM-Man O.E.M.-M	Aviation Device YES		Package OK	
Administrator: Sell			Department: ECYS1			Phone: 040 743 51261		

MAINTENANCE REPORT		Preliminary Inspection/HDI	Pre-Strip-Test YES	Cond. elec. OK	Cond. SW OK	Cond. mech. OK	BITE N/A
		Status of Removal Unjustified Removal		Tech. warranty YES		Missing Part NO	
Findings: Intensive testing performed. No faults encountered.							
Remarks: Work performed as per: CMM 23-73-10 Rev. 02 APR-04-2017.							
Work performed: Preliminary and hidden damage inspection performed; acceptance test successfully performed.							
							
Final Condition		PN_After Z150H0068110			SN_After 150H00001296		AMD_After A
Tested X	Repaired	Modified	Modified internal	Cond as is	Scrapped	Overhauled	
Warranty_Charge_WC C			NFF X	QA-Inspected 20 Okt. 2017			
Work performed staff Geiger		Work performed department ECYS3		Work performed date 13.10.2017			