

1. Approving Civil Aviation Authority/Country:

FAA/United States

4. Organization Name and Address:

LEADING EDGE AEROSPACE, LLC
16115 NW 52nd Ave
Miami Gardens, FL 33014
3LDR930C

2. **AUTHORIZED RELEASE CERTIFICATE**
 FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:

1184


5. Work Order/Contract/Invoice Number:

Work Order #: 1184
Cust. PO #: R12483

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
1	STRUT DRUM CONTROL BOX ASSY	315A1016-2	1	CN061	REPAIRED

12. Remarks:
 Unit REPAIRED in accordance with CMM ATA 76-11-14, Revision 27, Issued 7/1/2016. S/B and AD's: NONE complied with. Full details of work carried out held on Work Order 1184

Certifies that the work specified in Blocks 11/12 was carried out in accordance with EASA part 145 and in respect to that work the article is considered ready for release to service under EASA Part 145 Approval No. EASA.145.6727

13a. Certifies the items identified above were manufactured in conformity to: <input type="checkbox"/> N/A Approved design data and are in a condition for safe operation. <input checked="" type="checkbox"/> N/A Non-approved design data specified in Block 12.		14a. <input checked="" type="checkbox"/> 14 CFR 43.9 Return to Service <input checked="" type="checkbox"/> Other regulation specified in Block 12 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.	
13b. Authorized Signature:	N/A	13c. Approval/Authorization No.:	N/A
13d. Name (Typed or Printed):	N/A	13e. Date (dd/mm/yyyy):	N/A
14b. Authorized Signature:		14c. Approval/Certificate No.:	3LDR930C
14d. Name (Typed or Printed):	DANIEL FLORES	14e. Date (dd/mm/yyyy):	09/Feb/2018

User/Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Blocks 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.

LEADING EDGE AEROSPACE, LLC

Leading Edge
Aerospace



16115 NW 52nd Ave
Miami Gardens, FL 33014
Phone: (305) 222-7780 Fax: (844) 478-7649
E-Mail:
FAA #: 3LDR930C

Work Order #: 1184
Work Order Date: 01/04/2018

Cust#: 1823

RO#: R12483

Customer Name: SOURCE ONE SPARES

P/N: 315A1016-2

MFG: BOEING

Desc: STRUT DRUM CONTROL BOX ASSY

Model #:

Book#: LEA0112

Work Req: REPAIR

Trouble Reported: NONE

Rec Inspection: NO VISUAL DAMAGE, NSN, CONTROL NO, WILL BE ASSIGNED.

Special Instructions: PLEASE SEE R.O. FOR DETAILS

Preliminary P/N VERIFIED, S/N CN061 ASSIGNED.

Hidden Damage: NONE

Initial findings: UNIT HAS INTERNAL & EXTERNAL CONTAMINATION. RACK IS SEIZED.

Trouble Verified? Yes: No: N/A:
Bench Check? Passed Failed N/A:
Progressive findings: UNIT PARTIALLY DISASSEMBLED. UNIT HAS BENT RACK.

Corrective Action: DAMAGED PARTS REPAIRED OR REPLACED. UNIT REPAIRED I.A.W. MFG'S SPECS.

Work Performed: REPAIRED

AD Notes: SB's installed: NONE

P/N:	Description:	Qty:	Cond:	PO#:
315A1036-5	RACK	1	NS	1323
	CAD PLATE	1	NE	
	HARDWARE	1	NE	
	PAINT	1	NE	
	PAINT	1	NE	
	GREASE 33 AEROSHELL GREASE	1	NE	
	BMS5-63 SEALANT	1	NE	
	RTV157 ADHESIVE	1	NE	
	BACS12CK4U11 SCREW	1	NS	1338

1. **Имя:** ИВАНОВ ИВАН
 2. **Адрес:** Москва, ул. Ленина, д. 10
 3. **Телефон:** +7 495 123 4567
 4. **Почта:** ivanov@yandex.ru

01.01.2024
 12:30
 1000

Имя: ИВАНОВ ИВАН

Адрес: Москва, ул. Ленина, д. 10

Телефон: +7 495 123 4567

Почта: ivanov@yandex.ru

ИВАНОВ	ИВАН	ИВАНОВ
ИВАНОВ	ИВАН	ИВАНОВ
ИВАНОВ	ИВАН	ИВАНОВ
ИВАНОВ	ИВАН	ИВАНОВ
ИВАНОВ	ИВАН	ИВАНОВ
ИВАНОВ	ИВАН	ИВАНОВ

Имя: ИВАНОВ ИВАН

Адрес: Москва, ул. Ленина, д. 10

Телефон: +7 495 123 4567

Почта: ivanov@yandex.ru

Имя: ИВАНОВ ИВАН

Адрес: Москва, ул. Ленина, д. 10

Телефон: +7 495 123 4567

Почта: ivanov@yandex.ru

Имя: ИВАНОВ ИВАН

Адрес: Москва, ул. Ленина, д. 10

Телефон: +7 495 123 4567

Почта: ivanov@yandex.ru

Имя: ИВАНОВ ИВАН
 Адрес: Москва, ул. Ленина, д. 10
 Телефон: +7 495 123 4567
 Почта: ivanov@yandex.ru

Имя: ИВАНОВ ИВАН
 Адрес: Москва, ул. Ленина, д. 10
 Телефон: +7 495 123 4567
 Почта: ivanov@yandex.ru

Date: 02/09/2018

Technician: MARK SCHENCK

Inspector: DANIEL FLORES

Final Inspection

*Leading Edge
Aerospace*



LEADING EDGE AEROSPACE, LLC

16115 NW 52nd Ave

Miami Gardens, FL 33014

Phone: (305) 222-7780 Fax: (844) 478-7649

E-Mail:

FAA #: 3LDR930C

Work Order #: 1184

Work Order Date: 01/04/2018

The appliance/component identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration, is approved for return to service and is certified as airworthy.

Auth. Signature: _____

Your signature:

Уважаемый клиент! Мы рады видеть вас в нашем магазине. Если у вас возникли вопросы, пожалуйста, обращайтесь к нам. Мы всегда готовы вам помочь.

Дата: 05.08.2018

Подпись: Иван Иванович

М.П. ООО "Сбербанк"

Your profession:

Иван Иванович
М.П. ООО "Сбербанк"

Иван Иванович
М.П. ООО "Сбербанк"
ул. Ленина, д. 10
г. Москва, 125008
Телефон: 8000 000 000

М.П. ООО "Сбербанк" 05.08.2018