

1. Approving Civil Aviation Authority/Country
Transport Canada

2. **AUTHORIZED RELEASE CERTIFICATE FORM ONE**

3. Form Tracking Number:
WO12225

4. Organization Name and Address:
AJW Technique Inc
 7055, rue Alexander Fleming
 Saint-Laurent QC H4S-2B7
 Canada

5. Work Order, Contract or Invoice Number:
R245133-1

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial/Batch Number:	11. Status/Work:
1	Ground Power Control Unit	740121A	1.00	0130	INSPECTED/TESTED

12. REMARKS
 UNIT TESTED SERVICEABLE IN ACCORDANCE WITH CMM 24-41-07 REV. 22 DATED 25SEP2012.
 SEE TEAR DOWN REPORT FOR ADDITIONAL INFO.

PRINTED FROM ELECTRONIC FILE

EASA Approval No.: EASA.145.7260
 Maintenance performed in accordance with FAR 43.17

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in a condition for safe operation.
 Non-approved design data specified in Block 12

14a. Certifies that, except where otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was performed in accordance with Canadian Aviation Regulations.

CAR 571.10 Maintenance Release
 Other regulation specified in Block 12

13b. Signature:	13c. Approved Organization Number	14b. Signature	14c. Approval Organization Number
		<i>Daniel Hebert</i>	33-12
13d. Name (Typed or Printed):	13e. Date	14d. Name (Typed or Printed)	14e. Date (dd/mm/yyyy)
		Daniel Hebert	03/Nov/2014

Installer Responsibilities

This certificate does not constitute authority to install the part.

Installers working in accordance with the national regulations of a country other than specified in Block 1, must ensure that their regulations recognize certifications from the country specified.

Statements in blocks 13a or 14a do not constitute installation certification. In all cases, the technical record for the aircraft must contain an installation certification issued in accordance with the applicable national regulations before the aircraft may be flown.

Tear Down/Inspection Report

Work Order #: W012225

Date Printed: 03/11/2014

Customer RO: R245133-1

Page: 1

technique

7055 Alexander-Fleming st, suite 100, Saint-Laurent, QC, Canada, H4S 2B7

www.ajw-aviation.com



To:

A J WALTER AVIATION LTD
 THE HEADQUARTERS
 MAYDWELL AVENUE
 SLINFOLD, WEST SUSSEX RH13 0AS
 UNITED KINGDOM

Phone #: _____ Fax #: _____
 Code: AJW01 P/N: 740121A Serial #: 0130
 Descr: Ground Power Control Unit
 Qty: 1 Mfg: HAMILTON SUNDSTRAND

TSN: 0 TSO: 0 TSR: 0 CSN: 0 CSO: 0 CSR: 0
 P/N Out: 740121A Serial # out: 0130

Symptoms: CODE: REASON FOR REMOVAL
 DETAILS: Please test and report.

Faults: CODE: QUOTE
 DETAILS: PRELIMINARY INSPECTION (VISUAL):
 PART MISSING: NO
 DAMAGE FOUND (CID): NO
 HRS/CYCLE RECEIVED: NO
 ADDITIONAL REQUIREMENT:
 AD. SB, MOD, SIL NO
 ADD. CUST. REQUEST NO
 WARRANTY REQUESTED? NO
 TEST ARRIVAL:
 INITIAL TEST FAIL? NO
 REASON FOR REMOVAL CONFIRMED: YES
 DISASSEMBLY/INSPECTION:
 ANY ANOMALIES FOUND DURING DISASSEMBLY/INSPECTION
 WORK TYPE: TEST
 WORKSCOPE:
 CALIBRATION NO
 CLEANING NO
 OUT OF SCOPE NO
 OVERHAUL NO
 PAINTING NO

Tear Down/Inspection Report

Work Order #: W012225

Date Printed: 03/11/2014

Customer RO: R245133-1

Page: 2

technique



7055 Alexander-Fleming st, Suite 100, Saint-Laurent, QC, Canada, H4S 2B7

www.ajw-aviation.com

PCBR
REPAIR
REWORK
TIME CONTROLLED/TX
RE-QUOTE:
NO
NO
NO

CODE: TEST AND RECERTIFY
DETAILS: Initial test validated the operation and performance of the equipment and was found satisfactory.

Corrective Actions:
CODE: TESTED AS RECEIVED ONLY
DETAILS: Unit tested per CMM.