

AUTHORIZED RELEASE CERTIFICATE

FAA Form 8130-3, AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number:
56534

2. Approving Civil Aviation Authority/Country:
FAA/UNITED STATES

4. Organization Name and Address:
XTRA AEROSPACE INC.
15901 SW 29 Street, Suite 201, Miramar, FL 33027-5252, Fax 954/6340392, 954/3185073

Repair Station# IARR023B

5. Work Order/Contract/Invoice Number:
56534 / T21531

6. Item:	7. Description:	8. Part Number:	9. Quantity:	10. Serial Number:	11. Status/Work:
001	TRANSFER CYLINDER	273A2310-1	1	01052	REPAIRED

12. Remarks: **This item was Repaired I/A/W Manual # 32-40-01, Revision # 26 Revision Date 01/Nov/2014**
NO APPLICABLE AD'S AND NO S/B INSTALLED

Certifies that the work specified in block 11/12 was carried out in accordance with EASA Part 145 and in respect to that work the product/article is considered ready for release under EASA Part 145 Approval no.145.6136

13a. Certifies the items identified above were manufactured in conformity to:

Approved design data and are in condition for safe operation.


Non-approved design data specified in Block 12.

14a. 14 CFR 43.9 Return to Service Other regulation specified in Block 12

Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature:

13c. Approval/Authorization No.:

14b. Authorized Signature: 

14c. Approval/Certificate No.: **IARR023B**

13d. Name (Typed or Printed): **LUCAS E. CUADRA**

13e. Date (dd/mm/yyyy):

14d. Name: (Typed or Printed)

14e. Date (dd/mm/yyyy): **15/Jan/2015**

User/Installer Responsibilities

It is important to understand that the existence of this Document alone does not automatically constitute authority to install the aircraft/engine/propeller/article. Where the user/installer performs work in accordance with the national regulations of an Airworthiness Authority different than the Airworthiness Authority of the country specified in block 1, it is essential that the user/installer ensures that his/her Airworthiness Authority accepts aircraft engine(s)/propeller(s)/article(s) from the Airworthiness Authority of the country specified in block 1. Statements in block 13a and 14a do not constitute installation certification. In all cases aircraft maintenance records must contain an installation certification issued in accordance with national regulations by the user/installer before the aircraft may be flown.

WORK ORDER FORM 100



FAA CRS No: 1ARR023B

WORK ORDER: 56534-14

XTRA AEROSPACE INC.

15901 SW 29 Street, Suite 201

Miramar, FL 33027-5252

Fax 954/6340392

954/3185073

Customer: AJW001 / AJ WALTER AVIATION LTD.

Dept#:HYD

Location:

Cust RO#: T21531

Step:CLOSED

Warranty Code:00 /365

Mfg:BOEINGBOEING

*** NO PMA PARTS ***

Goodthru AD#:

Outgoing 273A2310-1 / TRANSFER CYL

S/N: 01052

Incoming P/N: 273A2310-1	
Incoming S/N: 01052	
Incoming Work Req.: BC	Outgoing Work Req: RE
Manual#: 1838	RevDate: 01/Nov/2014 Rev#: 26
	ATA: 32-40-01
Tools: A2134	
Reason/Rm: NONE STATED	
Date Recvd: 10/Dec/2014	Date Reqr'd: 16/Jan/2015
	Date Estmtd: 16/Jan/2015
PRELIMINARY INSPECTION: P/N AND S/N VERIFIED.	DATE: 16/Nov/2014 INSPECTOR: ORA
PRE TEST (Yes/No): Y	DATE: 16/Nov/2014 INSPECTOR: ORA
UNIT FAILED PRETEST DUE TO EXTERNAL LEAK FORM HOUSING JOINTS.	
HIDDEN DAMAGE: NONE NOTED.	
TEARDOWN FINDINGS: DISASSEMBLED, CLEANED AND INSPECTED IN ACCORDANCE TO BOEING CMM. UNIT REQUIRES ALL WORN, DISTURBED SEAL AND PACKING TO BE REPLACED, NDT, INSPECTED AS REQUIRED FOR REPAIR.	
TECHNICIAN:SXE	DATE: 17/Dec/2014 INSPECTOR: ORA
FINAL INSPECTION BEFORE ASSEMBLY:	DATE: 12/Jan/2015 INSPECTOR: ORR
CORRECTIVE ACTION: THE UNIT WAS DISASSEMBLED, CLEANED, INSPECTED, REPAIRED AS NECESSARY, ALL PACKINGS AND SEALS WERE REPLACED. NDT WAS PERFORMED, REASSEMBLED AND FUNCTIONALLY TESTED IN ACCORDANCE WITH THE MANUFACTURER SPECIFICATIONS.	
TECHNICIAN:HLP	DATE: 15/Jan/2015 INSPECTOR: LEC
MODIFICATION/SERVICE BULLETINS: *NO APPLICABLE AD'S AND NO S/B INSTALLED	
Test Data Used: ATA: 32-40-01 REV 26	DATE: 01/NOV/2014
Test Technician: HLP	DATE: 15/Jan/2015

Printed 16/Jan/2015

09:48:20

MPINIELL

Labor Task Control#



WORK ORDER FORM 100

XTRA AEROSPACE INC.
15901 SW 29 Street, Suite 201
Miramar, FL 33027-5252
Fax 954/6340392
954/3185073



FAA CRS No: TARR023B
WORK ORDER: 56534-14

Customer: AJW001 / AJ WALTER AVIATION LTD.

Dept#:HYD

Location:

Cust RO#: T21531

Step:CLOSED

Warranty Code: 00 /365

Mfg:BOEINGBOEING

*** NO PMA PARTS ***

Goodthru AD#:

Outgoing 273A2310-1 / TRANSFER CYL

S/N: 01052

Final Inspection:LEC

DATE: 15/Jan/2015

ADDITIONAL COMMENTS:

MAINTENANCE RELEASE RECORD

THE COMPONENT IDENTIFIED ABOVE WAS REPAIRED IN ACCORDANCE WITH THE CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION, AND IS APPROVED FOR RETURN TO SERVICE. OTHER PERTINENT DETAILS OF THE REPAIR ARE ON FILE AT THIS REPAIR STATION.

Approved For Return to Service by LUCAS E. CUADRA

Date 15/Jan/2015

XT
10

