

1. Approving Civil Aviation Authority / Country
FAA / United States

2. **AUTHORIZED RELEASE CERTIFICATE**
FAA Form 8130-3. AIRWORTHINESS APPROVAL TAG

3. Form Tracking Number
3210136255-F

4. ORGANIZATION NAME AND ADDRESS:
BARFIELD INC.
4101 N.W. 29TH STREET
MIAMI FL 33142-5617

 **BARFIELD**

5. WORK ORDER, CONTRACT OR INVOICE NUMBER
R247732 - 100000494139 / 100000494441

6. FAA REPAIR STATION No.: **XBIR995K**

6. ITEM	7. DESCRIPTION	8. PART NUMBER	9. QUANTITY	10. SERIAL NUMBER	11. STATUS / WORK
001	CARGO HEAT CONTROLLER	600611-00-506	1	20306	TESTED

12. Remarks :
 TSN/CSN UNK / UNK
 TSO/CSO UNK / UNK
 TSI/CSI 0 H / 0 C

Barfield certifies that the work specified in block 11/12 was carried out in accordance with EASA Part-145 and in respect to that work the component is considered ready for release to service under EASA Part-145 Approval Number : EASA 145.4239

13a. Certifies the items identified above were manufactured in conformity to
 Approved design data and are in a condition for safe operation.
 Non-approved design data specified in Block 12.

14a. 14 CFR 43.9 Return to Service
 Other regulation specified in Block 12
 Certifies that unless otherwise specified in Block 12, the work identified in Block 11 and described in Block 12 was accomplished in accordance with Title 14, Code of Federal Regulations, part 43 and in respect to that work, the items are approved for return to service.

13b. Authorized Signature :
 13c. Approval / Authorization No. : **XBIR995K**

14b. Authorized signature : *[Signature]*
 14c. Approval / Certificate No. : **XBIR995K**

13d. Name (Typed or Printed) :
 13e. Date (dd/mm/yyyy) :
 14d. Name (Typed or Printed) : **VICTOR JACQUES**
 14e. Date (dd/mm/yyyy) : **04/NOV/2014**

User / Installer Responsibilities

It is important to understand that the existence of this document alone does not automatically constitute authority to install the aircraft engine/propeller/article.

Where the user/installer performs work in accordance with the national regulations of an airworthiness authority different than the airworthiness authority of the country specified in Block 1, it is essential that the user/installer ensures that his/her airworthiness authority accepts aircraft engine(s)/propeller(s)/article(s) from the airworthiness authority of the country specified in Block 1.

Statements in Block 13a and 14a do not constitute installation certification. In all cases, aircraft maintenance records must contain an installation certification issued in accordance with the national regulations by the user/installer before the aircraft may be flown.



TEARDOWN REPORT

n° 3210136255

CUSTOMER	CUSTOMER	C000001374	A.J. WALTER AVIATION LTD
	REPAIR ORDER	R247732	
	WARRANTY		
	EXECUTION ORDER NUMBER	100000494139	
AIRCRAFT	AIRCRAFT	AIRBUS A320	
	SERIAL NUMBER		
ITEM RECEIVED	PART NUMBER	600611-00-506	
	SERIAL NUMBER	20306	
	DESCRIPTION	CARGO HEAT CONTROLLER	
	SERVICE REQUESTED	RP	REPAIR
ITEM DELIVERED	PART NUMBER	600611-00-506	
	SERIAL NUMBER	20306	
	DESCRIPTION	CARGO HEAT CONTROLLER	
	SERVICE RENDERED	BC	BENCH TEST
INSPECTED IN ACCORDANCE WITH	DOC.	21-43-01	REVISION 8
	TYPE	CMM	DATE 04/17/13

	TSN / CSN	TSO / CSO	TSI / CSI
HOURS	UNK	UNK	000000 H
CYCLES	UNK	UNK	000000 C
DATES			

REASON FOR REMOVAL	CROSS INDICATION FOR VALVES AND FAULT AT PF REPORT.		
	FAILURE CONFIRMED	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO <input type="checkbox"/> OTHER
REMARKS			
WARRANTY	<input type="checkbox"/> WARRANTY MANUFACTURER <input type="checkbox"/> WARRANTY REPAIRER		
CREATED BY			DATE NOV 04 2014

BARFIELD INC.
 4101 NW 29TH STREET
 MIAMI, FL, 33142
 USA
 Phone : +1 (305) 894 5300 - Fax : +1 (305) 894 5301

Repair Station No. XBIR995K



TEARDOWN REPORT

n° 3210136255

Work Description

Shop findings

1 PRELIMINARY INSPECTION

Corrective actions

1.1 NO UNUSUAL CONDITION NOTED

Shop findings

2 NO FAULT FOUND.

Corrective actions

2.1 TESTED UNIT W/I MFG SPECS.

(R) Reworked parts - (M) Missing parts upon arrival - (C) Parts provided by customer - (MC) Missing parts upon arrival and provided by customer

BARFIELD INC.
4101 NW 29TH STREET
MIAMI, FL, 33142
USA
Phone : +1 (305) 894 5300 - Fax : +1 (305) 894 5301
Form 7.5.3-6

Repair Station No. XBIR995K